## MCTX3420 Team 4: Progress Report #6

Rowan Heinrich, Callum Schofield, James Rosher, Justin Kruger, Jeremy Tan, Sam Moore

## Work Done:

- 1. Decide between JavaScript and Java GUI
  - a. Decided to stay with JavaScript GUI
- 2. Generate analog output on BeagleBone as required by Electronics team
  - a. Software has been written, but cannot be tested without BeagleBone
- 3. Add digital sensors/switches (GPIO pins) code to server side code
  - a. Software has been written, can't be tested without BeagleBone
- 4. Emailed Adrian, still no ETA on the BeagleBone
- 5. Improve GUI design and layout
- 6. Improve server API to meet GUI requirements
  - a. Server API is now versioned agreement between GUI and server over what is available
  - b. Can now query the server for a specific time range and number of points
- 7. Add sanity check function to check values of sensors are safe
- 8. Make potentiometer to test ADCs on beaglebone
- 9. Setup documentation generation using Doxygen

## Work Todo:

- 1. Deal with failure in sensor sanity check
  - a. Warning threshold and Emergency Threshold
  - b. Send log information and alerts to GUI
- 2. Plot sensor values vs actuator (pressure) values (not just time)
  - a. Two approaches; store data on server or process data in GUI
- 3. Improve Beaglebone sensors/actuator code for more general cases
  - a. Currently acts upon specific sensor/pin paths, should be a general function
- 4. Distinguish between individual experiments; start and stop functionality
  - a. Specify formula to automatically control actuator
- 5. Write test code to process an interferometer image

